# State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Day K

Michael O. Leavitt Governor Kathleen Clarke Executive Director

Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

# INSPECTION REPORT

Partial	Comp	lete XXX	_Expl	loratio	n
	tion Date:				
•		ast Inspec			

Mine Name: Banning Loadout County: Carbon	Permit Number: <u>C/007/034</u>						
Permittee and/or Operator's Name: Canyon Fuel Company							
Business Address: P.O. Box 1029, Wellington, Utah 84542							
Company Official(s): Vicky Miller, Engineering Technician							
State Official(s): Gregg Galecki Federal Official(s):							
Weather Conditions: Clear, 35 degrees F., slight breeze							
Type of Mining Activity: UndergroundSurfacePrep Pla	nt XXX Other						
Existing Acreage: Permitted 36 Disturbed 21.6 Regraded	Seeded						
Status: Temporary Cessation							

# REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	Ш	[X]	
2.	SIGNS AND MARKERS	[X]		[X]	$\Box$
3.	TOPSOIL	[X]	$\Box$	[X]	
4.	HYDROLOGIC BALANCE:				,
a.	DIVERSIONS	[X]	$\Box$	[X]	
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X]	
c.	OTHER SEDIMENT CONTROL MEASURES	[X]		[X]	$\Box$
d.	WATER MONITORING	[X]		[X]	$\Box$
e.	EFFLUENT LIMITATIONS	[X]	$\Box$	[X]	$\Box$
5.	EXPLOSIVES		[X]		
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	$\Box$	[X]		
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		[X]		
8.	NONCOAL WASTE	[X]		[X]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	[X]		$\Box$	
10.	SLIDES AND OTHER DAMAGE		[X]		
11.	CONTEMPORANEOUS RECLAMATION		[X]		$\Box$
12.	BACKFILLING AND GRADING		[X]	$\Box$	
13.	REVEGETATION	[X]		[X]	Щ
14.	SUBSIDENCE CONTROL		[X]		
15.	CESSATION OF OPERATIONS	[X]		[X]	
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[X]		لِـلِ	ĻĻ
b.	DRAINAGE CONTROLS	[X]	Щ	لِـاً	Ļ
17.	OTHER TRANSPORTATION FACILITIES	[X]	Щ	Ļ	Ļ
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	Щ	لِيَا	Ļ
19.	AVS CHECK (4th Quarter- April, May, June)	[X]	Ц	$\coprod$	Ļ.ļ
20.	AIR QUALITY PERMIT	[X]	Ļ	[X]	닌
21.	BONDING & INSURANCE	[ <u>X]</u>	1_1	[X]	$\sqcup$

## INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: C/007/034 DATE OF INSPECTION: 02/26/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

**Note:** The Banning site remains in temporary cessation; there is no activity at the site.

## 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The current UPDES permit for the Banning Siding remains in affect until April 30, 2003.

The Division completed the midterm permit review for Banning Siding on June 1, 2001 with no issues pending.

Amendment AM01D allowed for the storage of Sediment Pond material from the Dugout Mine to be placed at the site. The amendment was approved, executed, and As-builts have been submitted and approved.

## 2. SIGNS AND MARKERS

Identification signs meet the requirements of the R645 Coal Rules. The perimeter markers were spot-checked and are located around the perimeter of the disturbed areas.

#### 3. TOPSOIL

The Banning Siding site was completed and brought into full operation in 1978. As most of the earthwork was completed prior to the passage of SMCRA in August of 1977, there was no topsoil salvaged for reclamation purposes.

#### 4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversion around the fence line was checked and was found to be adequate to comply with the Hydrology Coal Section of the R645. Diversions were dry during the inspection.

# 4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The fourth quarter impoundment inspection for the site's sediment pond was conducted on November 20, 2001, with no signs of instability or other hazards being reported. Mr. Dave Spillman and Ms. Vicky Miller conducted that inspection. This pond is incised. An inspection of the pond was conducted by DWQ personnel on February 7, 2002, which concurred the stability of the pond.

## 4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Due to the addition of sediment pond material to the site, a series of berms was placed around both sediment pond material stockpiles. All material was contained within the first berm for both stockpiles. No sediment transport was noted.

## 4D. HYDROLOGIC BALANCE: WATER MONITORING

The fourth quarter water monitoring data for the Banning Siding Loadout was not available for the February 27, 2002 inspection, with the exception of the DMR sheets. The one water monitoring site (Truck dump sump), is required to be sampled annually in late fall. Field notes indicated the sample was collected on December 10, 2001.

#### INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/034</u>

DATE OF INSPECTION: 02/26/2002

#### 4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

Discharge monitoring reports for the months of October, November, and December of 2001 were reviewed. There were no outfalls from the sediment pond during this period. All reports were submitted in a timely fashion.

As noted during today's field inspection, the sediment pond was dry. No problems were noted.

#### 8. NONCOAL WASTE

The area was clear of non-coal waste material.

## 13. REVEGETATION

Sediment from the Dugout sedimentation pond has been roughened and seeded. No cover is present on the seed. The site was dry, free of snow, and no germination of seeds was observed.

# 15. CESSATION OF OPERATIONS

The Banning Loadout entered temporary cessation of operations on May 5, 2000, and ended coal sampling on December 8, 2000. No change in status has occurred.

# 20. AIR QUALITY PERMIT

The Air Quality permit was issued July 16, 1980. No modifications to the permit have been observed.

#### 21. BONDING AND INSURANCE

The general liability insurance for this CFC site expires on July 31, 2002.

Inspector's Signature:

Gregg A. Galecki

Date: February 27, 2002

Note:

This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc:

James Fulton, OSM Rick Olsen, Canyon Fuel Dave Spillman, Canyon Fuel

Price Field office

O:\007034.BAN\Compliance\2002\c\_0226.doc